

عمليات تشغيل المعادن (1) السنة الأولى - قسم الهندسة الصناعية

Answer the Following Questions

Question No. (1)

(14 Points)

- 3 a) Explain with drawing the main elements of the cutting tool turning, its angles and the function of each angle?
- 3 b) The failure of cutting tool can be classified into two categories. Explain?
- 3 c) Define the cutting motion and feed motion, and show by drawing the cutting motion and the feed motion in turning, shaping and drilling processes.
- 3 d) What is the difference between shaping and planning? Give sketch for basic geometry of shaping and planning?
- 4 e) A slab milling operation is being carried out on a 30-in.-long, 10-in.-wide high strength steel block at a feed of 0.02-in./tooth and a depth of cut of 0.2-in. The cutter has a diameter of 3.5-in., has eight straight cutting teeth, rotates at 150 rpm, and the cutting force 125 lbf. Calculate MRR, CT, the power required (at the spindle), the specific horse power, and the horse power for the motor.

(Note: The efficiency of the motor 80% and $CF = 1.5$).



Question No. (2)

(14 Points)


- 3 a) Explain with net drawing how does face milling differs basically from peripheral milling. In addition, explain why there are different types of milling cutters?
- 3 b) Explain with net drawing the selection of cutting tool material, geometry and the cutting condition for a given application?
- 3 c) What are the main characteristics required for the cutting tool. Mention two different types of the cutting tool material and the advantages of each type.
- 3 d) Explain by drawing five different types of turning processes?

Q3

(a) the chip is formed by a localized shear process that takes over a very narrow region. This large strain, high strain plastic deformation evolves out of a radial compression zone that travels ahead of the tool as it passes over the work piece.




वेदुता




Workpiece material have high ductility

वेदुता



Workpiece material have high hardness

वेदुता




Workpiece material have medium ductility

Q3

(c)

(14)



1- F_c : Primary cutting force acting in the direction cutting velocity vector $F_c \approx 99\%$ of the

2- F_f : feed force acting in the direction of the tool feed

$$F_f = 50\% F_c$$

3- F_r : radial or thrust force acting perpendicular to the machine surface.

$$F_r = 50\% F_f$$

$$F_{\text{total}} = \sqrt{F_c^2 + F_f^2 + F_r^2}$$

قوة الكلي = الجذر التربيعي لمجموع مربعات القوى الثلاثة

Q 3

(16)

③

$$D = 2 \text{ in}$$

$$N_1 = 284$$

$$T_1 = 10$$

$$N_2 = 232$$

$$T_2 = 60$$

Req V_3 ? $T_3 = 30 \text{ min}$ given.
 N_3 ?

$$V_1 T_1^n = V_2 T_2^n = C$$

$$V_1 = \frac{\pi D N_1}{12} = \frac{\pi * 2 * 284}{12} = 149 \text{ ft/min}$$

$$V_2 = \frac{\pi D N_2}{12} = \frac{\pi * 2 * 232}{12} = 122 \text{ ft/min}$$

$$\frac{V_1}{V_2} = \left(\frac{T_2}{T_1}\right)^n \Rightarrow \frac{149}{122} = \left(\frac{60}{10}\right)^n$$

$$1.22 = (6)^n \quad \ln 1.22 = n \ln 6$$

$$\boxed{n = 0.11}$$

$$V_3 T_3^n = C \Rightarrow V_3 * (30)^{0.11} = C$$


$$V_1 T_1^n = C \Rightarrow C = 149 (10)^{0.11} = 192$$

→ Question 4

a) Explain with drawing the shaper mechanism for drawing Tool Post with

in shaper, the cutting tool is held in the tool post located in the ram which reciprocates over the work with each stroke, cutting at velocity V and a quick return at velocity V_R . The rpm rate of the drive crank drives the ram and determines the velocity of the the stroke ratio

$$R_s = \frac{\text{Cutting stroke angle}}{360^\circ} = \frac{200^\circ}{360^\circ} = \frac{5}{9}$$



Question with answer of the division device, shown above and if we need to make gears with 24 Teeth, how we will set the division device?

The dividing head is by far the most widely used machine accessory, provide a means of holding and indexing work through any desired arc of rotation. The work may be mounted between centers, or held in a chuck that is mounted the spindle hole of the dividing head.

Basically, the dividing head is rigged accurate 40:1 gear reduction unit. The spindle of the dividing head is rotated one revolution by turning the input crank on an index plate mounted beneath the crank. Containing a number of holes arranged in concentric circles and equally spaced each circle have a different # of holes, a longer pin on the crank handle can be adjusted to engage the holes of any circle as represented by the increment between any two holes of a circle on the index plate.

$$\text{where } \# \text{ of turns of crank} = \frac{40}{\text{cut per revolution of}} \\ \# \text{ holes to be indexed} = \frac{40 \times \# \text{ hole in index}}{\text{cuts per revolution}}$$

— if we Required a gear with 24 Teeth

$$\therefore \frac{24}{40} = 2 \frac{2}{3}$$

Q4

(e)

Given

$$V = 135 \text{ ft/min}$$

$$A = 0.004 \text{ in}^2$$

$$d = 0.08 \text{ in}$$

$$E = 0.8$$

$$K_{s.1.1} = 129032 \text{ I}$$

$$Z = 0.26$$

$$CF = 1.5$$

Req

HP_{at spindle}

وقت

HP_{motor}

$$F = b \cdot h \cdot k_s = A \cdot k_s$$

$$A = b \cdot h, \quad b = d = 0.08 \text{ in}$$

$$0.004 = 0.08 \cdot h$$

$$h = 0.05 \text{ in}$$

$$k_s = K_{s.1.1} / h^Z = 129032 / (0.05)^{0.26}$$

$$k_s = \frac{129032}{0.46} = 280504 \text{ Ib/in}^2$$


$$F_c = 0.004 \cdot 280504 = 1122 \text{ Ib}$$

$$HP = \frac{F_c \cdot V}{33000} = \frac{1122 \cdot 135}{33000} = 4.59 \text{ hp}$$

Question 5

a) explain with drawing the component of Grinding wheel.
why there are different types of Grinding wheel.

- The Grinding wheel consists mainly of abrasive material and bonding material.
- The abrasive particles accomplish cutting.
- Bonding material holding particles in place and establish shape and structure of wheel.



There are different types of Grinding wheel depending

the Geometry, the grain size, the abrasive material type

the type of bonding material & the density of

abrasive particles

Q) What are the advantages of using cutting fluids?

Cutting fluids (also called lubricants and coolants) and it is used in machining operation to:

1- cool the cutting zone so it help to reduce work piece temperature, distortion and in the tool life.

2- reduce friction and wear so it improves tool and surface finish.




3- reduce the required forces and energy consumption.

4- wash away chips.

5- protect the newly machined surface from oxidation.


E)

on milling "vertical milling"



and on shaping machine

F



Question No. (3)


(14 Points)

- 3 a) Explain by drawing the fundamental mechanism of chip formation, the different types of chip and the conditions for each type?
- 3 b) Explain with drawing the main element of the twist drill and the function of each element?
- 3 c) Explain with drawing the components of cutting force and its percentage. Explain briefly the importance to determine the cutting force?
- 3 d) Mention the main sources of heat in machining. Explain the distribution of heat generated in machining and how we can overcome this generated heat?
- 4 e) When a 2 in diameter steel is turned on a lathe at $N = 284$ rpm the cutting tool changed after 10 min. if the spindle rotates at $N = 232$ rpm the cutting tool changed after 60 min. calculate the cutting speed when the cutting tool changed after 30 min and also calculate the rotating speed of the spindle?

Question No. (4)

(14 Points)

- 3 a) Explain with drawing the shaper (quick return) mechanism for driving tool and work?
- 3 b) Explain with drawing (counter boring – counter sinking – spot facing)?
- 3 c) Explain with drawing the division head, how it works and if we need to make a gear with 24 teeth. How we will set the division device?
- 3 d) Mention the different methods for making taper turning? And calculate the taper angle for the following product?




- 4 e) It is required to machine a bar of steel in a turning machine with a cutting speed of 135 ft/min, chip cross-section 0.004 in^2 and depth of cut 0.08 in. Where K is equal to 129032 lb/in^2 . Determine:
 - (i) Cutting force


Question No. (5)

(14 Points)

- 3 a) Explain with drawing the component of grinding wheel, and why there are different types of grinding wheels?
- 3 b) Explain the relation between cutting speed and cost per price?
- 3 c) What are the advantages of using cutting fluid?
- 3 d) Explain with drawing the steps to get the following final product from the given raw material using turning machine?



Raw material




Final product


- 4 e) Explain with drawing the steps to get the following final product from the given raw material?



Raw material




Final product



Q1

(a)



الزاوية α (rake angle) هي زاوية القاطع مع السطح العمودي على اتجاه القاطع. كلما كانت هذه الزاوية أكبر، كلما كان القطع أسهل. (موصوف - صالح - هجر)

الزاوية β (clearance angle) هي الزاوية بين السطح الخلفي للقلم والسطح العمودي على اتجاه القاطع. كلما كانت هذه الزاوية أكبر، كلما كان القطع أسهل.

الزاوية ϵ (approach angle) هي زاوية مقدمة القلم مع السطح العمودي على اتجاه القاطع. كلما كانت هذه الزاوية أكبر، كلما كان القطع أسهل.

الزاوية β (tool angle) هي الزاوية بين السطح الخلفي للقلم والسطح العمودي على اتجاه القاطع. كلما كانت هذه الزاوية أكبر، كلما كان القطع أسهل.

Q1


c

- cutting motion (speed v) relates the velocity of rotating workpiece with respect to the stationary tool.

رغم نسبة سرعة العدة (أداة إقطع)، الشغل قد تأخذها أداة إقطع من عمليات (التفريز - التفتيح - التبريد) وقد تأخذها مثل (الخراطة).

- Feed motion (Feed f_r) is the amount of the material per revolution or per pass of the tool over the work

عمره إقتاب الشغل من العدة أو العدة من الشغل (التفريز - التبريد) من العدة المقاطعة مزيد من الخافرة ليتم عليها إزاله إرغيش



(6)

$$HP_{\text{at spindle}} = \frac{F_c V}{33000} = \frac{125 * V}{33000}$$

$$V = \frac{\pi D N}{12} = \frac{\pi * 3.5 * 150}{12} = 137.4 \text{ ft/min}$$

$$HP_{\text{at spindle}} = \frac{125 * 137.4}{33000} = 0.52 \text{ hp}$$

$$HP_s = \frac{HP}{MRR} = \frac{0.52}{48} = 0.011 \text{ hp (in}^3/\text{min)}$$

$$HP_m = \frac{HP_s * MRR * CF}{E} = \frac{0.52 * 1.5}{0.8}$$

$$HP_m = 0.975 \text{ hp}$$


(7)

Q2

(a)


- Face milling: The surface generated is at right angle to the cutter axis

الوجهين يكون محور سكينه لتقيرز متعامداً على السطح المشغل



- Peripheral milling: The surface is parallel with the axis of rotation of the cutter

العاوي يكون السطح المشغل موازياً لمحور سكينه لتقيرز



بأنواع مختلفه كالتاليه لتقيرز تبعاً لما يلي :

وهي اسنانها هل هي على كحيط ام على الواجهه

لفطرسكينهت ضعيفاً جداً وأخرى كبيرة لتتناسب مع أسطح المشغلات

عدد الاسنان فهو كبير عند تقيرز المعادن الصلده و صغيره للمعادن اللدنه

لأنها كلما حتى عمكه أنتاج مجارى ترس، لولب، السطح مستوية

شكل مجارى الرأس فهي إما مستقيمه، او منحنية او هلزونية .

9

42

©

لخص التي يجب توفرها من أدوات القطع

لبيانها لخص الصفوة الناتجة من عملية القطع، وإعطاء مثال

صلادة السطح العالية لمقاومة الاحتكاك الناتج من أشياء كثيرة

الصلادة العالية لضمان إتقان عمل من مادة واحدة واستمرار القطع

تحت الحرارة العالية لضمان عدم فقدان الصلادة أثناء عملية القطع

Briefly the cutting tool should have good (strength, hardness,

toughness, wear resistance and hot hardness)

Tool steel

- Carbon steels and low/medium alloy steels (called tool steels)
- tool steels lose hardness at temperature above 400°F because of tempering
- low/medium-alloy steels have alloying element such as Mo and Cr which improve hardenability and W and Mo which improve wear resistance
- Low/medium alloy steels materials also lose their hardness at $300-650^{\circ}\text{F}$

High speed steel

- high alloy steel was superior tool steel that is retained its ability at temperature up to exhibiting good (red hardness) with Carbon steel.
- cutting speed HSS = double cutting speed tool steel with equal
- HSS contain significant amount of W, Mo, Co, V and Cr that hardness and wear resistance
- HSS is still widely used

Q2
e

②

$$W = 10 \text{ in} \quad L = 8 \text{ in} \quad V = 150 \text{ ft/min}$$

$$f_c = 0.02 \text{ in per stroke}$$

$$L \Rightarrow \text{stroke length} = 2L$$

$$L = 2 \times 8 = 16 \text{ in}$$

$$V = \frac{2L N_s}{12 R_s}$$

$$150 = \frac{2 \times 16 \times N_s}{12 \times 5/9}$$

$$N_s = 31.25 \text{ rpm}$$

$$CT = \frac{W}{N_s f_c} = \frac{10}{31.25 \times 0.02} = 16 \text{ min}$$

$$S = \frac{W}{f_c} = 500 \text{ strokes.}$$